



STAGE 04 組裝副駕駛儀表板



STEP 01

將 2 顆 AAA 電池裝入電路板組件(第2期完成品)。
接上 4-P(C 線材)。 LED 指示燈應亮起。
測試完成後請拔除線材，並取出電池。

Insert 2x AAA batteries into the circuit board(stage 02).
Connect 4-P (cable C). The LEDs should light up.
Disconnect the cable and remove the batteries after testing.




STEP 02

將 4-P 放置於 4-B 上。使用 2 顆 CP 螺絲固定。
Place 4-P onto 4-B. Screw the parts together using 2x CP.



STEP 03

將 4-M 壓入 4-A。
Push 4-M into 4-A.



STEP 04


將 C 線材穿過 4-A。接著將 4-A 與 4-B 組合並壓緊固定。
Thread cable C through 4-A. Join 4-A and 4-B. Press together.



STEP 05


將 4-C 與 4-D 壓入 4-A。
Press 4-C and 4-D into 4-A

建議等收到第5期，
5J裝好後再繼續安裝



STEP 06

將 4-N 剪裁成四個部分。
每張水貼使用前請先浸泡於清水中約 30 秒。
Cut 4-N into four sections.
Soak each decal in water for 30 seconds before applying.



STEP 07

將水貼 C 貼附於組件上。
請確認方向正確。
Apply decal C to the assembly.
Check the orientation is correct.



STEP 08

依照圖示將水貼 D 與水貼 B 貼附於組件上。
請仔細確認貼附方向。
Apply decals D and B to the assembly as shown.
Check the orientation carefully.



STEP 9

將零件 4-G 放置於 4-E 與 4-F 下方。
Place parts 4-G underneath 4-E and 4-F.



STEP 10

將 4-E 與 4-F 黏貼至 4-A。
請小心操作，避免損壞水貼或使膠水沾附於水貼表面。
Glue 4-E and 4-F onto 4-A.
Take care not to damage or get glue on the decals.



STEP 15

將 C 線材穿過駕駛艙框架組件 (第3期, STEP14零件)。
Thread cable C through the cockpit frame assembly (stage 03, step 14).




STEP 11

將 4-J 放置於 4-H 下方。
請仔細參考圖片，確認安裝方向正確。
Place 4-J underneath 4-H. Study the picture carefully to ensure the correct orientation.



STEP 12

將水貼 A 貼附於 4-K，然後將其放置於 4-H 下方。
Apply decal A to 4-K then place it underneath 4-H.



STEP 16

小心地將本組件裝入駕駛艙框架內。
請注意不要損壞駕駛艙框架上的任何脆弱零件。
Carefully push the assembly into the cockpit frame.
Take care not to damage any of the fragile parts on the cockpit frame.



STEP 17

使用 1 顆 DP 螺絲固定。
Screw the parts together using 1x DP.



STEP 13

將 4-H 壓入 4-L。
Push 4-H onto 4-L.



STEP 14

將 4-L 壓入 4-A。
Push 4-L into 4-A.

建議可等第5期5S、5T零件
裝好後再裝入4A

STAGE COMPLETE

